

## **Read Me**

### **System Software 9.1.8 Patch 7 SED**

**Deutsch** Folgende Fehler sind in Systemsoftware 9.1.8 Patch 7 korrigiert worden:

#### **1.1 VoIP - Kein Notruf möglich**

**(ID 19307)**

In bestimmten Konfigurationen konnte es vorkommen, dass ein Notruf über SIP nicht abgesetzt werden konnte.

#### **1.2 Telefonie - Wave-Datei nicht abgespielt**

**(ID 19481)**

Bei einem hohen Aufkommen von Telefonaten konnte es vorkommen, dass eine Wave-Datei, die bei einer automatischen Rufannahme abgespielt werden sollte, unterbrochen oder gar nicht abgespielt wurde.

#### **1.3 VoIP - Ruf abgewiesen**

**(ID 19486)**

Es konnte vorkommen, dass ein eingehender VoIP-Ruf mit der Statusmeldung "480 (Temporarily not available)" abgewiesen wurde.

#### **1.4 VoIP - Abbruch eines SIP-Rufs**

**(ID 19445)**

Bei Gesprächen über bestimmte SIP Provider konnte es vorkommen, dass der Ruf nach etwa 30 Minuten beendet wurde.

## **1.5 VoIP - Kein Ruf von der Hauptnummer**

**(ID 19373)**

Es konnte vorkommen, dass Rufe von der Hauptrufnummer eines Anschlusses nicht möglich waren und vom System eine andere Rufnummer verwendet wurde. Gelegentlich kam es auch dazu, dass eingehende Rufe nicht möglich waren.

## **1.6 VoIP - Verbindungsabbruch**

**(ID 18964)**

Es konnte gelegentlich zum Abbruch von SIP-Verbindungen kommen, die auf ein Mobiltelefon weitergeleitet wurden.

## **1.7 Telefonie - Lange Wartezeit bei Registrierung**

**(ID 19417)**

Wenn ein System über Auto Configuration Server (TR-069) konfiguriert wurde, so brauchten Rufnummern circa 10 Minuten, um sich zu registrieren.

## **1.8 Telefonie - Falsches Rufnummernformat**

**(ID 19447)**

Bei einem Ruf von einem System zu einem zweiten wurde ein falsches Rufnummernformat verwendet.

## **1.9      Telefonie - Keine kommenden Rufe**

**(ID 18878)**

Mit dem SIP-Provider toplink waren keine kommenden Rufe möglich.

**English** The following errors have been corrected in system software 9.1.8 Patch 7:

## **1.1 VoIP - Emergency call impossible**

**(ID 19307)**

In specific configurations it could occur that emergency calls via SIP were not possible.

## **1.2 Telephony - Wave file not played**

**(ID 19481)**

If there was a high telephony load, playback of a wave file that was to be played after an automatic call pick-up was interrupted or not even started.

## **1.3 VoIP - Call rejected**

**(ID 19486)**

Incoming VoIP calls were occasionally rejected with the status message "480 (Temporarily not available)".

## **1.4 VoIP - Interrupted SIP call**

**(ID 19445)**

Calls via certain SIP providers were occasionally interrupted after ca 30 minutes.

## **1.5 VoIP - No call from the main subscriber number**

**(ID 19373)**

Occasionally, calls from the main subscriber number of a connection were not possible and the system used a different number to initiate a call. Additionally, incoming calls were occasionally not possible.

## **1.6 VoIP - Connection interrupted**

**(ID 18964)**

There were occasional interruptions of SIP calls that were transferred to a mobile phone.

## **1.7 Telephony - Long waiting period during registration**

**(ID 19417)**

Configuring a device via Auto Configuration Server (TR-069) caused a registering period of phone numbers of about ten minutes.

## **1.8 Telephony - Wrong phone number format**

**(ID 19447)**

If one device called another, a wrong phone number format was used.

## **1.9 Telephony - No incoming calls**

**(ID 18878)**

No incoming calls were available via SIP provider toplink.