

## Read Me

### System Software 9.1.7 Patch 5 WNY/INY

Deutsch Folgende Fehler sind in Systemsoftware 9.1.7 Patch 5 korrigiert worden:

#### 1.1 WLAN - Schlechte Sprachübertragung bei VoWLAN

(ID 18428)

Bei der Übertragung von Voice over WLAN konnte es zu unzureichender Übertragungsqualität im Zusammenhang mit UAPSD (Unscheduled Automatic Power Save Delivery) kommen.

#### 1.2 WLAN - Multicast-Verbindung gestört

(ID 18993)

Bei einer Verbindung mit einem bintec WLAN-Gerät der Wx003n- bzw. Wx004n-Reihe kam es zu Störungen des Multicast-Verkehrs.

#### 1.3 Roaming-Verbesserungen

(ID n/a)

Wenn sich beim Client Roaming der Client nicht beim Access Point abmeldete, konnte es vorkommen, dass der Access Point weiterhin versuchte, Daten an den Client zu schicken, und dadurch unnötig Air Time beanspruchte.

**English The following errors have been corrected in system software 9.1.7 Patch 5:**

## **1.1 WLAN - Insufficient voice quality with VoWLAN**

**(ID 18428)**

During voice transmission with Voice over WLAN voice quality was occasionally insufficient when UAPSD (Unscheduled Automatic Power Save Delivery) was involved.

## **1.2 WLAN - Multicast connection failure**

**(ID 18993)**

In connections with a bintec WLAN device of the Wx003n and Wx004n series, multicast traffic was disturbed.

## **1.3 Roaming Improvements**

**(ID n/a)**

If a roaming client did not sign off from the access point, the access point occasionally kept trying to send messages to the client and needlessly claimed air time.