

Known Issue

System Software 10.1.x

Deutsch Folgendes Problem ist bekannt:

1.1 SIF-Adress-Aliase

Wenn Sie in der Konfiguration Ihres Geräts Adress-Aliase in der SIF verwenden, könnte es bei einem Update von 9.x auf 10.1.x zu Problemen mit Ihrem Gerät kommen. Wir empfehlen Ihnen in diesem Fall, das Update zu verschieben, bis wir Ihnen die Lösung des Problems zur Verfügung stellen.

Sollten Sie bereits ein Update von 9.x auf 10.1.x vorgenommen und die Konfiguration nach dem Update gespeichert haben, so müssen Sie die Adress-Aliase neu konfigurieren.

Sollten Sie sich aus dem Gerät ausgesperrt haben und lokalen Zugang zum Gerät haben, so können Sie sich über die serielle Konsole einloggen.

English The following problem may arise:

1.1 SIF Address Aliases

If you are making use of address aliases in the SIF configuration of your device, there may be problems when updating the system software from a 9.x release to a 10.1.x release. In this case, we recommend postponing the update until we offer a solution for this problem.

If you have already carried out an update from a 9.x release to a 10.1.x release and have saved the configuration after the update, you need to reconfigure the address aliases.

If you have shut yourself off from your device, you can connect through the serial console.

